


























PAX 01











I5  M6x12 x32	L6  6mm x1			
 x2	I6  30x30 x7	I5  x22	P6  x4	P7  x1
L3a  x1	L3b  x1	G2  x2		
N30  M6x15 x28	A6  6x50 x4	B4  ø8x50 x5	N50  M6x100 x9	
	L4  4mm x1	N51  M6x100 x4		


I






N50		
		
x2		x3

G2	B4	P7
		
x2	x2	x1






N50		x6
M6x100		

G2		x2
----	---	----



B4		x3
ø8x50		


III




15		x4
M6x12		
L6		x1
6mm		




IV




15		M6x12	x28
L6		6mm	x1


V




N51				x4
M6x100				
A6		L4		x4
6x50	x4	4mm		x1
		G2		x2

VI




L4	P6	N30
4mm	x1	M6x15
		
	x4	x16

VII




L4



4mm

x1


N30




M6x15

x8

VIII




IX



N30
M6x15
x4




L3a



x1

L3b



x1

I6



30x30

x7

X

